



ME1118 CW

Eff.	Watts	Volts	Amps	RPM
1.00-	5000-	100-	100-	5000-
0.90-	4500-	90-	90-	4500-
0.80-	4000-	80-	80-	4000-
0.70-	3500-	70-	70-	3500-
0.60-	3000-	60-	60-	3000-
0.50-	2500-	50-	50-	2500-
0.40-	2000-	40-	40-	2000-
0.30-	1500-	30-	30-	1500-
0.20-	1000-	20-	20-	1000-
0.10-	500-	10-	10-	500-
0.00-	0-	0-	0-	0-



www.electrictmotorsport.com