



ME1906

24V CW 09.9.24

Eff.	Watts	Volts	Amps	RPM
1.00-	5000-	50-	200-	5000-
0.90-	4500-	45-	180-	4500-
0.80-	4000-	40-	160-	4000-
0.70-	3500-	35-	140-	3500-
0.60-	3000-	30-	120-	3000-
0.50-	2500-	25-	100-	2500-
0.40-	2000-	20-	80-	2000-
0.30-	1500-	15-	60-	1500-
0.20-	1000-	10-	40-	1000-
0.10-	500-	5-	20-	500-
0.00-	0-	0-	0-	0-





LBIN

ME1906

24V CCW 09.9.24

Eff.	Watts	Volts	Amps	RPM
1.00-	5000-	50-	200-	5000-
0.90-	4500-	45-	180-	4500-
0.80-	4000-	40-	160-	4000-
0.70-	3500-	35-	140-	3500-
0.60-	3000-	30-	120-	3000-
0.50-	2500-	25-	100-	2500-
0.40-	2000-	20-	80-	2000-
0.30-	1500-	15-	60-	1500-
0.20-	1000-	10-	40-	1000-
0.10-	500-	5-	20-	500-
0.00-	0-	0-	0-	0-





LBIN

ME1906

36V CW 09.9.23

Eff.	Watts	Volts	Amps	RPM
1.00-	5000-	50-	200-	5000-
0.90-	4500-	45-	180-	4500-
0.80-	4000-	40-	160-	4000-
0.70-	3500-	35-	140-	3500-
0.60-	3000-	30-	120-	3000-
0.50-	2500-	25-	100-	2500-
0.40-	2000-	20-	80-	2000-
0.30-	1500-	15-	60-	1500-
0.20-	1000-	10-	40-	1000-
0.10-	500-	5-	20-	500-
0.00-	0-	0-	0-	0-





LBIN

ME1906

36V CCW 09.9.23

Eff.	Watts	Volts	Amps	RPM
1.00-	5000-	50-	200-	5000-
0.90-	4500-	45-	180-	4500-
0.80-	4000-	40-	160-	4000-
0.70-	3500-	35-	140-	3500-
0.60-	3000-	30-	120-	3000-
0.50-	2500-	25-	100-	2500-
0.40-	2000-	20-	80-	2000-
0.30-	1500-	15-	60-	1500-
0.20-	1000-	10-	40-	1000-
0.10-	500-	5-	20-	500-
0.00-	0-	0-	0-	0-




LBIN

ME1906

48V CW 09.9.24

Eff.	Watts	Volts	Amps	RPM
1.00	10000	50	200	5000
0.90	9000	45	180	4500
0.80	8000	40	160	4000
0.70	7000	35	140	3500
0.60	6000	30	120	3000
0.50	5000	25	100	2500
0.40	4000	20	80	2000
0.30	3000	15	60	1500
0.20	2000	10	40	1000
0.10	1000	5	20	500
0.00	0	0	0	0





RPM	
Amps	
Volts	
Watts Out	
Eff.	

ME1906

48V CCW 09.9.24

Eff.	Watts	Volts	Amps	RPM
1.00	10000	50	200	5000
0.90	9000	45	180	4500
0.80	8000	40	160	4000
0.70	7000	35	140	3500
0.60	6000	30	120	3000
0.50	5000	25	100	2500
0.40	4000	20	80	2000
0.30	3000	15	60	1500
0.20	2000	10	40	1000
0.10	1000	5	20	500
0.00	0	0	0	0



LBIN