

72V ME1908 (ME0709) CW

Eff.	Watts	Volts	Amps	RPM
1.00-	20000-	100-	500-	5000-
0.90-	18000-	90-	450-	4500-
0.80-	16000-	80-	400-	4000-
0.70-	14000-	70-	350-	3500-
0.60-	12000-	60-	300-	3000-
0.50-	10000-	50-	250-	2500-
0.40-	8000-	40-	200-	2000-
0.30-	6000-	30-	150-	1500-
0.20-	4000-	20-	100-	1000-
0.10-	2000-	10-	50-	500-
0.00-	0-	0-	0-	0-

